


NOTES:

1. INSTALL BASE SCREWS WITH LOCTITE.
2. LABEL THE UNCONNECTED CAP LEAD WITH A #8 WIRE MARKER.
3. INSTALL CONNECTION LABEL UNDER CONDUIT BOX LID.

CUSTOMER IS RESPONSIBLE FOR DETERMINING THAT MOTOR PERFORMANCE IS SUITABLE IN THE APPLICATION.

REV. DESC: CORRECT THRUBOLT LOC			BALDOR ELECTRIC Co.
REV. LTR: A	VERSION: 01	TDR: 000000387012	
25E633W005	FILE: \CKA\00026\585	REVISED: 07:08:11 01/27/2006	LY,25AC MTR EXR TENV W\BASE (25E068W005)
	MTL: –	BY: CKRONS0	

25E633W005