

34LY6173





CUSTOMER IS RESPONSIBLE FOR DETERMINING THAT BALDOR'S PRODUCT WILL PERFORM SUITABLY IN THE INTENDED APPLICATION.

REV. DESC: REMOVE "RED" FROM SEALER NOTE		
REV. LTR: K	VERSION: 02	TDR: 000001035460
FILE: \AAA\00021\311	REVISED: 02:33:37 07/14/2017	BY: ENMAIYO
MTL: –		

BALDOR

STD HORZ 34PM TEFC IEC D71D B35 2P W/M.F.T.K.

SH 1 of 1

34LY6173