




# Semiconductor Fuse 50-400A, 1250 Volts

BIF Document  
**17056630**  
Size **1\***



The partial dotted curves are for fuses designed to give part range protection (aR protection). Loading or operation above the curve indicated at A on the curves must in general be avoided. Please see technical guidance 170K... for further information. Curves that are not dotted are for fuses designed to give full range protection.



**Pre-Arcing** Time-Current Characteristic Curves  
**TYPOWER ZILOX**

|                  |               |                  |               |
|------------------|---------------|------------------|---------------|
| Approved: _____  | <b>PK</b>     | Page _____       | <b>1 of 2</b> |
| Rev. Date: _____ | <b>FEB-99</b> | Pub. Date: _____ | <b>NOV-94</b> |



Semiconductor Fuse  
50-400A, 1250 Volts

BIF Document  
**17056630**  
Size **1\***



**Peak Let-Through** Cut-Off Current Characteristic Curves  
**TYPOWER ZILOX**

Approved: **PK** Page **2 of 2**  
Rev. Date: **OCT-94** Pub. Date: **NOV-94**