



### TTMA Flanged Sight Flow Indicators

Size	Nominal Width	Acrylic	
		Part #	Price/E
3"	1 3/4"	<b>TT3ASG</b>	<b>\$116.00</b>
4"	1 3/4"	<b>TT4ASG</b>	<b>116.00</b>
3"	1 3/4"	<b>TT3ASG-ETH</b> <sup>1</sup>	<b>370.00</b>
4"	1 3/4"	<b>TT4ASG-ETH</b> <sup>1</sup>	<b>370.00</b>

#### Optically Enhanced Sight Glass

Size	Nominal Width	Acrylic	
		Part #	Price/E
3"	1 3/4"	<b>TT3ASGOE</b>	<b>\$130.00</b>
4"	1 3/4"	<b>TT4ASGOE</b>	<b>130.00</b>
3"	1 3/4"	<b>TT3ASG-ETHOE</b> <sup>1</sup>	<b>370.00</b>
4"	1 3/4"	<b>TT4ASG-ETHOE</b> <sup>1</sup>	<b>370.00</b>



<sup>1</sup> for use with ethanol

- For flange dimensions, diagrams and additional information please reference dixonvalve.com.

### Sight Flow Indicator Repair Kits

Description	Used on	Part #	Price/E
3" replacement sight glass, Baylast™ O-ring and retainer ring kit	---	<b>5200-SFI-3-RK1</b>	<b>\$80.75</b>
3" replacement sight glass, FKM O-ring and retainer ring kit	---	<b>5200-SFI-3V-RK1</b>	<b>149.60</b>
4" replacement sight glass, Baylast™ O-ring and retainer ring kit	---	<b>5200-SFI-RK1</b>	<b>80.75</b>
4" replacement sight glass, FKM O-ring and retainer ring kit	---	<b>5200-SFIV-RK1</b>	<b>149.60</b>
replacement Baylast O-rings, sight glass and retaining ring	5201-SFI	<b>5201-SFI-RK1</b>	<b>84.45</b>
Buna-N O-ring	---	<b>O249BU</b>	<b>4.75</b>
plexiglass insert	---	<b>4PSG</b>	<b>84.00</b>
Buna-N O-ring	---	<b>O246BU</b>	<b>4.25</b>




5200-SFIV-RK1

### TTMA Flange Screen

**Feature:**

- stainless steel screen is encapsulated in an FKM gasket

Male NPT	Description	Stainless Steel	
		Part #	Price/E
2"	screen with 1" square holes	<b>TTFS4SS</b>	<b>\$150.00</b>



- For flange dimensions, diagrams and additional information please reference dixonvalve.com.