CONNECTION DETAILS FOR GROUP C **OUTPUT VOLTS** CONNECT TO LINE FOR RESPECTIVE VOLTAGE X1-X3 H1-H4 H1-H2 H1-H3 H1-H5 X1-X2 500 85 100 208 220 380 440 550 91 110 95 115 230 400 460 575 240 416 480 600 99 120 H1 H2 H3 416V 400 380 440 440 120V 115 110 100 Х3 X1 X2

| Acme Electric° | | | | |
|----------------|-----------------|--|--|--|
| | | | | |
| | | | | |
| Type No. | | | | |
| | | | | |
| | | | | |
| Date: | August 26, 2010 | | | |
| | | | | |
| | Г | | | |
| | | | | |
| | | | | |
| | | | | |

Revisions

X1-X4

110

120

125

130

| VA | CATALOG NUMBER | VOLTAGE | | WIRING | WEIGHT | PHASE | FREQ. | | |
|---------------------------|----------------|-------------|-------------|---------|--------|-------|----------|--|--|
| | | HIGH | LOW | DIAGRAM | | | | | |
| 1000 | FS-3-1000 | See Diagram | See Diagram | | 39 Lbs | 1ф | 50/60 Hz | | |
| TYPICAL PEDEOPMANICE DATA | | | | | | | | | |

PRINTS

TO

A

CONTROL

7

| Temp. Rise: | 80°C | | TYPICAL PERFORMANCE DATA | | | | | |
|--------------|-------|------|---|------|------------------|--|----------------|--|
| Insulation: | 130°C | Stan | Standard UL/CSA/CE Impedance: Full Load | | Full Load Losses | | | |
| Windings: CU | | | FINGER/GUARD | | | | No Load Losses | |
| Α | В | С | D | Е | F | | | |
| 6.18 | 6.75 | 6.03 | 5.75 | 4.30 | .31 x .50 | | | |